

# THE BLIND SHOP


## Measuring Guide

### Clic Blinds


#### USEFUL TIPS

- Use a metal tape measure
- Measurements should always be in centimetres
- Measure the width first followed by the drop (width x drop)
- Measure all windows even if they appear to be the same

1. Measure the width of the glass area of your window at the top, middle and bottom. Measure from where the beading meets the glass. Note the smallest measurement. This is the WIDTH measurement.



2. Measure the height of the glass area of your window. Measure from where the beading meets the glass. This is the DROP measurement.



Any questions? Call us on 01273 462196

THE BLIND SHOP

[theblindshop.com](http://theblindshop.com)